



IQ Engine 10.5r3

Release Notes

December 2022



Copyright © 2022 Extreme Networks, Inc. All rights reserved.

Legal Notice

, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice.

Trademarks

and the logo are trademarks or registered trademarks of , Inc. in the United States and/or other countries.

All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners.

For additional information on trademarks, see:

Open Source Declarations

Some software files have been licensed under certain open source or third-party licenses. End-user license agreements and open source declarations can be found at: <https://www.extremenetworks.com/support/policies/open-source-declaration/>



Table of Contents

General Release Information.....	4
Release Date.....	4
Hardware platforms supported.....	4
Management platforms supported.....	4
New Features.....	5
Known Issues.....	6
Addressed Issues.....	7



General Release Information

Release Date

December 2022

Hardware platforms supported

- AP130
- AP250
- AP650
- AP5050D
- AP5050U
- AP122
- AP230
- AP1130
- AP150W
- AP550
- AP30
- AP305C/CX
- AP305C-1
- AP302W
- AP510C/CX
- AP410C
- AP410C-1
- AP460C,
- 460s6C
- 460S12C
- AP4000
- AP4000-1
- AP5010
- AP5050D
- AP5050U

Management platforms supported

ExtremeCloud IQ 22.7.0 and later



New Features

The release introduces the following new hardware:

- AP5050D
- AP5050U

Spectrum Analyzer Support Expanded

The Spectrum Analyzer now supports the AP4000.



Known Issues

Issue ID	Description
HOS-17683	Some WPA3 clients cannot associate to the AP4000 properly when band steering is enabled. Workaround: Disable band steering.
HOS-18492	AP250: iPhone13 and Pixel 6 cannot connect to WPA3 WLAN while Fast Transition (FT) is enabled.
HOS-18432	AP4000: Client (Pixel 6) cannot roam with WPA3 Fast Transition (FT)
CFD-7445 (02496570, 02626393, 02651353)	802.11ax client, such as iPhone 12/13, experiences difficulties when receiving 11ac frames if the MCS rate >5 on a Wave1 chip platform, such as AP230, AP122, and AP130. Workaround: Use 11AC Phymode with lower MCS rates (from 0-3), or use 11N Phymode.



Addressed Issues

Issue ID	Description
HOS-18169	AP5000: Antenna power is low on a 6Ghz 40Mhz channel.
HOS-18016	Roaming in Client Mode on the AP302W is fixed.
CFD-7195 (02449306, 02478299, 02582108)	AP does not respond to Network Solicitation (NS) or icmpv6 type 135 with SLAAC.
CFD-8698 (7777777)	PPSK accounts failing to assign proper role.